



Property Inventories

Sample Check Out Report

123 London Road, London, N1 0PP

Visit date: March 9th 2021 Clerk: Property Inventories

020 7812 0490

www.propertyinventories.com info@propertyinventories.com

This sample report contains excerpts from the original report and is for demonstration purposes only. Property Inventories. All Rights Reserved.

Contents

Notes	2
Checklists	5
Areas	6
Schedule of Condition	6
Keys	8
Meter Readings	9
Front Entrance	1
Entrance Hallway	13
Kitchen	1
Reception	2
Bathroom	3:
Bedroom	4
Actions	4

Notes

Disclaimers:

Check-out reports are used to give landlords / managing agents an independent, third party view of the condition of a property and its contents at the end of a tenancy. The check-out report provides comments on differences in condition compared to the original inventory and check-in report supplied to the inventory clerk by the managing agent / landlord. Note that these original reports may not have been prepared by Property Inventories Ltd, so there may be some unknowns, which will be highlighted in this report. Where reference numbers were included in the original inventory, we try to include these same numbers in the check-out report for ease of reference.

This check-out report has been prepared at the end of the tenancy using an unsigned inventory and check-in report prepared by Property Inventories Ltd.

When the inventory clerk visits the property to prepare the check-out report, they will update the inventory they are supplied with by hand to reflect any changes to the previous comments. The check-out report then provides a typed listing of these comments, while the new, annotated 'working inventory' is returned to the managing agent / landlord for further use if they wish. The inventory clerk also gives their opinion on liability of any comments on condition noted in the check-out report. Where no comments on a particular item are included in the check-out report, the comments and descriptions in the original working inventory remain applicable to the current state of the property and no further comments are necessary. Property located in cellars, attics and locked rooms and / or boxes will typically not be inspected and will remain the sole responsibility of the landlord. Some heavy items and furniture may not be fully examined as the clerk may not be able to move these safely (for example, the underside of large mattresses). We test lights, fire alarms and / or smoke detectors to check working ability. Gas, electrical appliances are not tested. The Inventory Clerk compiling the report for the property is not qualified to test these items. The Fire and Safety Regulations regarding furniture, electrical, gas and other similar appliances are ultimately the responsibility of the instructing party and not Property Inventories Ltd. Where the inventory states 'FFR label seen', this should not be taken to mean that the furniture actually complies with the regulations, merely that the label was viewed on the furniture at the time the inventory was undertaken.

Abbreviations Used:

AN: Appears new

MCA: Marks commensurate with age

PC: Poor condition **BOG:** Burnt on grease

MCU: Marks commensurate with use **RFC:** Requires further cleaning

FS: Finger soiled
NS: Not seen
RHS: Right-hand-side
FC: Fair condition
NT: Not tested

SC: Shrinkage cracking GC: Good condition NW: Not working TBR: To be removed

L: Landlord

NV: No value

WIU: Well in use

LHS: Left-hand-side

ODU: Old defects under

WO: Working order

This inventory report has been prepared by Property Inventories Ltd. The condition of the property at the start of the tenancy, as described in this report, will be compared to the condition of the property at the end of the tenancy. Details of any alterations to the property after the inventory has been agreed upon should be noted on a separate sheet and agreed upon by the tenant and managing agent/landlord. At the end of the tenancy, a 'Check-out report' should be conducted to determine any changes to the inventory. Tenants should inform the managing agent/landlord of items removed from the property during the tenancy.

All items should be returned to their original position (as laid out in the inventory); this includes stored or boxed items not used during the tenancy. Any item(s) listed as NOT SEEN could result in a replacement cost or a charge being made to the tenant (not allowing for betterment*). Managing agents/landlords may also charge for the removal of unapproved items left behind at the end of the tenancy that were not included in the original inventory.

At the time of the property Check-out, all personal items (including consumable items) should have been removed and cleaning of the property completed. No further cleaning will be permitted once the check-out report is being prepared. Tenants will have been given the date and time of the Check-out and must provide access, or let the appointing Inventory Clerk know the details of their departure from the property. Additional costs may be incurred if the clerk is not able to complete the report, is delayed more than 20 minutes or is asked to return at another time without 24 hours notice.

The following notes may assist you in a problem-free move at the end of the tenancy:

Cleaning

Soiling is not considered to be 'Fair Wear and Tear' (reasonable use of the premises by the tenant and the ordinary operation of natural forces, i.e. the passage of time)

At Check-out, all cleaning is expected to be thorough and the property to be presented in a tidy order to a similar standard as at Check-in. A professional clean may be required by the agent/landlord (please refer to your tenancy agreement). If the standard of cleaning is not satisfactory, the cost of further cleaning could be added to any other charges outside fair wear and tear on the Check-out report. Most common areas overlooked, which are checked by the clerk during the Check-out are listed below:

- Skirting boards, dado & picture rails and recessed areas of doors, light fitting and shade, blinds
- (Venetian blind slats) and extractors are free from dust and light scuffs
- Light bulbs replaced where needed (including kitchen extractor fans, oven and fridge)
- Mildew, scale, soap residue and grease, to be removed from tiled areas including grout and seals
- Kitchen cupboards (door edges, drawers, shelves, and handles) to be clean
- Kitchen appliances should be cleaned to include seals, trays, and glass.
- Fridge and freezers should be emptied, wiped and freezers defrosted
- Bathroom and kitchen fixtures limescale to be removed, if possible. (including shower heads)
- Linens and curtains should be cleaned (please check labels for cleaning instructions)
- Drawers and wardrobe unit interiors should be clean and clear of dust / debris
- Windows should be cleaned (inside and out, subject to access)
- Upholstery, sofa bases, cushion covers and dining/other chairs to be cleaned (please check labels)
- Gardens, including any garden furniture and/or patios to be clean and clear of rubbish

Soft Furnishings

Excessive discolouring, soiling or damages may result in repair or cleaning costs being charged to the tenants. Discolouration due to smoke, staining, burn marks or tears to curtains may also incur costs.

*Improvement beyond normal upkeep and repair that adds to the value of real property

Flooring

Carpets should be vacuumed including edges and corners. Depending on the terms of the tenancy agreement and/or the length of tenancy, flooring should be professionally cleaned. Please retain all receipts for such work. Hard floors require sweeping and mopping where necessary (please use appropriate chemicals). Tenants may be charged for any soiling or staining and will incur costs for damage such as heavy stains and burns. If flooring is badly damaged you may be charged for the cost of replacement without allowing for betterment.

Decorations

It is advisable to ask for permission prior to putting nails, pins and other fixtures into walls and avoid putting tack or tape on walls. This is often not allowed under most the tenancy agreements. All additional marks will be noted at Check-out and any damage or repair work in order to make good any marks could be charged to the tenant.

Beds & Linens (to include bedding)

Mattresses, bed bases, pillows, and duvets will be examined for soiling where practically possible. Charges could be made for cleaning, compensation or a percentage of the replacement cost. All linen should be left cleaned, pressed and folded.

Kitchen Surfaces and Sinks

Kitchen surfaces and sinks will be examined for knife cuts, cup marks, scorch and burn marks. Using appropriate items such as chopping boards and heat pads will help prevent damage.

Crockery, chinaware, and kitchen utensils

All items will be checked for soiling, chips, burn marks, loose handles etc. If damage has occurred outside of fair wear and tear, compensation or replacement costs could be incurred at the end of the tenancy.

Keys

All keys listed in the inventory should be kept safely and handed back at the end of the tenancy. Should any keys be lost or not returned to the agent or Inventory clerk, the tenant may be charged replacement costs for new cut keys or possibly the changing of locks. Any extra keys cut during the tenancy should also be returned.

Gardens & Balconies

If a gardener is not employed for the property, you will be required to maintain the garden. This includes the cutting of lawns, weeding, and maintaining the garden according to the season. If the standard is found to be untidy and not within season, the tenant may be charged for any necessary work at the end of the tenancy. We recommend asking permission prior to removing any plants or trees as this may result in replacement costs.

Smoke Alarms / Alarm systems

Alarms have been tested by the Inventory Clerk where accessible and noted in the report.

Checklist

Item	Value	Comments
Keys detailed / photographed?	Yes	See Keys section
Maintenance Issues?	Yes	Brown water stains to reception wall
Overall Condition	Yes	Property Cleanliness In the opinion of the inventory clerk, the property has been cleaned to a good domestic standard and is shown in a tidy condition, including flooring and windows
		Decorative Order The property is shown in good decorative order with marks and defects where noted in report
		Maintenance / Repair Issues Any maintenance / repair issues have been noted in the report
Keys Handed Over?	No	Keys collected from tenant and returned to agent
Meter Readings Taken?	Yes	See Meters section
Smoke / CO Alarms	Yes	All tested and in WO

1. Schedule Of Condition

Item	Condition at Check In	Condition at Check Out
General Cleanliness		
1.1 Professional/Domestic/Poor Standard	The property has been cleaned to a professional standard with omissions	The property has been cleaned to a good domestic standard with omissions
Decorative Order		
1.2 Decorative Order	The property is shown in good decorative order	As Check In + Water penetration stains to reception wall
Lighting		
1.3 Condition/Cleanliness	WO	As Check In
Smoke / CO Alarms		
1.4 Tested / WO	All tested and in WO	As Check In
Windows & Frames		
1.5 Condition/Cleanliness	Cracks to 1 pane in bathroom No catch seen for bathroom window handle	As Check In
Blinds / Curtains		
1.6 Condition/Cleanliness	Good order	As Check In
Flooring		
1.7 Condition/Cleanliness	Light debris	As Check In
Fridge & Freezer		
1.8 Condition/Cleanliness	Good order	Light food residue in places Cracks to shelf panel
Hob		
1.9 Condition/Cleanliness	Usage marks to burners	As Check In
Oven		
1.10 Condition/Cleanliness	Light chip to top	As Check In
Cooker hood		
1.11 Condition/Cleanliness	WO	As Check In
Dishwasher		
1.12 Condition/Cleanliness	None	As Check In

Page 6 of 54 123 London Road, N1 0PP

1. Schedule Of Condition (Cont.)

Washer / Dryer		
1.13 Condition/Cleanliness	Good order	As Check In + Soap residue to tray Light soiling to exterior
Exterior Areas		
1.14 Garden / Front Approach	None	As Check In

2. Keys



Ref #2

Item	Description
2.1 Flat door	2 1 Chubb 2 1 Yale
2.2 Block door	2 1 Yale

3. Meter Readings

Item	Serial Number	Reading at Check In	Reading at Check Out
Meters			
3.1 Electric	Serial Number: XXXXXX Location: Built in cupboard in kitchen	02642	65485.4
	6 5 4 10000 1000 1000 1000 1000 1000 1000 1	# 3.1	
3.2 Gas	Serial Number: XXXXXX Location: Built in cupboard in kitchen	02189.343	06853.665
	Ref	# 3.2	

Page 9 of 54 123 London Road, N1 0PP

4. Front Entrance

Item	Description	Condition at Check In	Condition at Check Out
(External) Front Door & A	Architrave		
4.1 Door	Medium wood Chrome plate low level	Soil spots Discolouration Marks in places	As Check In + 2 Removal holes above lock Indents to mid level opening edge Scratches above lock Sticker residue to opening edge Explain/Repair - Tenant FWT Clean - Tenant
4.2 Door Frame	Painted black wood		Scattered angle chips FWT
Door Fixtures			
4.3 Numerals	Chrome '369'		
4.4 Lever handle	Chrome		Not seen Explain/Replace - Tenant
4.5 Lock	Chrome		
4.6 Letterbox	Chrome	Red marks	As Check In
4.7 Mortice lock	Chrome	Item added after Check In	Not previously mentioned Explain/Remove - Tenant
(Internal) Front Door & A	rchitrave		
4.8 Door	Medium wood	Rubs below lock Silvering low level	As Check In + Circular indents and 2 removal holes below night latch Explain/Repair - Tenant FWT
4.9 Door Frame	Painted white wood	Painted over defects Occasional light rubs	As Check In + Angle chips Light scuffs FWT
Door Fixtures			
4.10 Closing arm	Grey metal Briton		
4.11 Doorknob	Chrome	Slightly loose	Not seen Explain/Replace - Tenant

Page 10 of 54 123 London Road, N1 0PP

4. Front Entrance (Cont.)

4.12 Mortice lock	Chrome		Now seen as chrome twist lock Explain/Replace - Tenant
4.13 Reverse of letterbox	Chrome		
4.14 Night latch and catch		Item added after Check In	Not previously mentioned Explain/Remove - Tenant

Page 11 of 54 123 London Road, N1 0PP

5. Entrance Hallway





	D-	ű

Item	Description	Condition at Check In	Condition at Check Out
Ceiling			
5.1 Ceiling	Painted white		
Ceiling mounted fixtures			
5.2 Ceiling rose, cord, pendant, bulb	White plastic	WO	As Check In
5.3 Smoke Alarm	White plastic	Tested and in WO	As Check In
	Ref	# 5.3	
5.4 Fixture	White metal Circular	Use unknown	As Check In
5.5 Extractor fan	White plastic	NT	As Check In
Walls			
5.6 Walls	Painted white		Rub marks mid to low level LHS Rubs to RHS of bedroom 1 Rubs to RHS of entrance FWT

Page 12 of 54 123 London Road, N1 0PP

5. Entrance Hallway (Cont.)



Ref # 5.6

Wall mounted fixtures			
5.7 Entry phone	Entroview White plastic Integrated screen	NT	As Check In + Light dust Clean - Tenant
Switches & Sockets			
5.8 White plastic switches and sockets as fitted to include:	Isolator switch		Minor dust to top Clean - Tenant
Woodwork			
5.9 Skirting	Painted white		Light to moderate dust to top Clean - Tenant
Flooring			
5.10 Floorboards	Medium wood effect laminate Chrome doorstop		
Built In Cupboard			
5.11 Door, frame and fittings	White painted wooden door White painted wooden frame Chrome lever handles with matching cuffs		Indentation to LHS of door frame Rub marks to centre door frame

Page 13 of 54 123 London Road, N1 0PP

Ref # 5.11

5. Entrance Hallway (Cont.)

5.12 Built in cupboard interior

Ceiling - painted white Walls - painted white Skirting - painted white wood Floor - continuation from hallway Not fully examined due to height Rub marks throughout Dust to top of skirting FWT

Clean - Tenant

5.13 Built in cupboard contents

White laminate shelf Chrome hanging rail White plastic socket White plastic smoke alarm White plastic light fitting and bulb Smoke alarm tested and in WO

As Check In + Hangers in situ

Explain/Remove - Tenant

6. Kitchen







Ref #6

Item	Description	Condition at Check In	Condition at Check Out
Door & Architrave			
6.1 Door	Painted white wood	Painted over defects	As Check In + Blue marks above exterior handle Small angle chip to mid level opening edge Faint splash marks to mid level exterior Clean - Tenant FWT



Ref # 6.1

6.2 Door Frame Painted white wood Painted over defects

As Check In +
Scattered residue spots
Angle chip to high level RHS
Clean - Tenant FWT



Ref # 6.2

Page 15 of 54 123 London Road, N1 0PP

Door Fixtures

6.3 Lever handle

Brass

White paint spots

As Check In + Scratches Residue to interior handle FWT Clean - Tenant







Ref # 6.3

Ceiling

Painted white 6.4 Ceiling

Ceiling Mounted Fixtures

6.5 Bulk light

White and obscure plastic Chrome and obscure glass WO

As Check In

6.6 Smoke alarm

White plastic

Tested and in WO

As Check In



Ref # 6.6

6.7 Carbon monoxide alarm

White plastic Εi

Tested and in WO

As Check In

Page 16 of 54 123 London Road, N1 0PP



Ref # 6.7

Walls

6.8 Painted

Cream

Tape residue to high level between built in cupboards Brown soil spots to mid level between built in cupboards Shading to same area Further tape residue RHS to window Further tape residue, filled in hole and splash marks LHS to cooker hood Light rubs below light switch Heavy residue marks and soil spots below cooker hood Clean - Tenant FWT

Explain/Repair - Tenant



Ref # 6.8



Ref # 6.8



Ref # 6.8



Ref # 6.8



Ref # 6.8

6.9 Tiled

White tiles white grouting

Discolouration to grouting

As Check In

Wall Mounted Fixtures

6.10 Extractor fan

White plastic

Soiling Clean - Tenant



Ref # 6.10

6.11 Pipe

Metal

Windows & Frames

6.12 Window casement

White uPVC 2 Movable panes 1 Fixed pane White lockable lever handles Excess paint

As Check In +
Brown discolouration to frames
Light soiling to handles and
trickle vents

FWT

Clean - Tenant



Ref # 6.12



Ref # 6.12

6.13 Reveals

As walls

6.14 Sill

As splashback

Discolouration to grouting

As Check In

Heating

6.15 Double panelled radiator

White manufacturer's finish with grille

NT
Both end caps seen
Yellow residue to top
Dust to inside
Dust to top

As Check In

Switches & Sockets

Page 18 of 54 123 London Road, N1 0PP

6.16 White plastic switches and sockets as fitted to include:

2 Double sockets Fuse switch Light switch Cooker switch Light soiling spots
Clean - Tenant



Woodwork		

6.17 Skirting	Painted white wood	Painted over defects	As Check In
Flooring			
6.18 Tiles	Black with silver grouting	Light debris to floor	As Check In + Furniture indentations below fridge Rucking below washing machine and forward of kickboards FWT



Ref # 6.18



Ref # 6.18

Kitchen Units

6.19 Kitchen units

Light wood units Chrome D-handles Slight swelling and discolouration to edge of wall unit LHS of cooker hood FWT

Page 19 of 54 123 London Road, N1 0PP



Ref # 6.19

6.20 Wall units

2 Single units

1 Double unit

6.21 Base units

4 Single units Double under sink unit Light usage marks FWT

Light usage marks Faint discolouration to rear wall of under side unit Bowing, swelling and debris to under sink unit shelf FWT

Explain/Repair - Tenant

Clean - Tenant



Ref # 6.21

6.22 Drawers

5 Drawers 1 Faux drawer

Light usage marks FWT

Worktops & Splashbacks

6.23 Worktop

Grey marble effect

Mould to sealant behind sink

Clean - Tenant

6.24 Splashback

White tiles with grouting

Discolouration to grouting

As Check In

Sinks / Taps

6.25 1 Sink with integrated dish drainer, overflow, waste, chain and plug

Stainless steel

Water marks Sponges to interior

Clean - Tenant

Explain/Remove - Tenant

Page 20 of 54 123 London Road, N1 0PP





Ref # 6.25

Ref # 6.25

6.26 Mixer tap with single control

Chrome

Water marks Clean - Tenant

Appliances

6.27 Cooker hood

White plastic *Micromark* 2 Lights Glass visor

Fan and lights in WO

As Check In + Loose to wall 1 Bulb NW

Replace Bulb - Tenant



Ref # 6.27

6.28 Hob

BekoIntegrated with oven Induction
4 Burners

NT Usage marks to burners As Check In







Ref # 6.28

Page 21 of 54 123 London Road, N1 0PP

6.29 Oven

Beko Model No.: KDG611W 6 White plastic dials 2 White metal D-handles LED display 2 Chrome tracks Black metal baking tray with chrome

NT Light chip to top Clean - Tenant







Ref # 6.29

Ref # 6.29

Ref # 6.29

6.30 Fridge freezer

White Beko

trivet

Model No.: CRFG3582W

Fridge to include: 2 White plastic wire shelves Clear glass shelf with white plastic trim Clear plastic salad crisper 3 Clear plastic door shelves White plastic 6-piece egg holder

Freezer to include: 2 White plastic wired trays NT

As Check In + Light food residue in places Cracks to shelf to panel

xplain/Repair - Tenant







Ref # 6.30

Ref # 6.30

Ref # 6.30



Ref # 6.30

6.31 Washing machine

Amica Model No.: KDG611W* NT

As Check In +
Soap residue to tray
Light soiling to exterior
Clean - Tenant



Ref # 6.31



Ref # 6.31



Ref # 6.31



Ref # 6.31

6.32 Boiler

VaillantWhite manufacturer's finish

NT

As Check In + Light residue to front and side Clean - Tenant

Page 23 of 54 123 London Road, N1 0PP





Ref # 6.32

Ref # 6.32

Built in cupboard

6.33 Door, frame and fixtures

Painted white wood Brass doorknob

Scattered residue spots and dark marks Angle chip to opening edge of LHS cupboard door

Clean - Tenant FWT





6.34 Built in cupboard interior

Grey brick Brick floor

Wear

As Check In + 3 Screws to walls of LHS built-in cupboard

Explain/Remove - Tenant



Ref # 6.34



Ref # 6.34

6.35 Built in cupboard contents

Gas meter Electricity meter Fuse box Pipe

Page 24 of 54 123 London Road, N1 0PP

Furnishings			
6.36 Additional items	Glass tumblers Mugs Bowls Shot glasses Juicer Dish drainer 2 Foldable chairs Red dustpan and brush Red handle - seen behind pipework in LHS built in cupboard Assortment of manuals 3 Cream roller blinds 3 Black roller blinds Light shade Further miscellaneous items	Item added after Check In	Not previously mentioned Explain/Remove - Tenant

Page 25 of 54 123 London Road, N1 0PP

7. Reception

7.4 Ceiling

Ceiling mounted fixtures

Painted white





Re

	Ref #7		Ref #7	
Item	Description	Condition at Check In	Condition at Check Out	
Door & Architrave				
7.1 Door	Painted white wood Recessed panel	Occasional paint chips	As Check In + Scratches to mid level exterior Light finger marks above interior handle Drip marks below interior handle FWT Clean - Tenant	
Ref#	7.1 Re	f # 7.1	Ref # 7.1	
7.2 Door Frame	Painted white wood	Occasional paint chips	As Check In	
Door Fixtures				
7.3 Pair of lever handles with matching backplates	Brass	Usage marks Tarnished	As Check In + Loose Paint chips Maintenance - Landlord FWT	
Ceiling				

Page 26 of 54 123 London Road, N1 0PP

Minor split forward of entry

As Check In

7.5 Ceiling rose, cord, pendant and bulb

White plastic

WO Discolouration and dust to cord As Check In + Cobwebs

7.6 Smoke alarm

White plastic

Tested and in WO

As Check In



Ref # 7.6

Walls

7.7 Painted

Cream

Several pin holes to high level LHS of chimney breast Filled in removal hole to high level RHS of entry Notable angle chip to mid level RHS of window Notable discolouration below window Rubs in places

As Check In + Notable tears to corner RHS of entry door Further scattered small tears to lining paper Several pin holes to mid level throughout White plastic hook to RHS edge of recess RHS of entry door Water penetration stains below window

Explain/Remove - Tenant



Ref # 7.7



Ref # 7.7



Ref # 7.7







Ref # 7.7

Ref # 7.7







Ref # 7.7

Ref # 7.7

Ref # 7.7







Ref # 7.7

Windows & Frames

7.8 Window casement

Painted white metal 3 Movable panes 3 Fixed panes 2 Chrome lever handles Faint run marks to glass Paint flaking and discolouration to frames Minor black mould spots Water penetration to low level Swelling to low level RHS of

As Check In

Brass lever arm

Tarnishing to handles

7.9 Reveals

As walls

Dark stains to high level

As Check In

Window Coverings

Page 28 of 54 123 London Road, N1 0PP

7.10 Venetian blinds

White wood Matching cord, cords and acorns WO Light discolouration, dust and residue marks to slats, cords, acorns and rod One acorn broken and seen to floor

As Check In + Crack to 1 slat to mid level RHS Explain/Repair - Tenant







Ref # 7.10

Ref # 7.10

Ref # 7.10

Heating

7.11 Antique-style radiator

Painted cream metal

both end caps seen Minor paint chips and cracks As Check In

Switches & Sockets

7.12 White plastic switches and sockets as fitted to include:

2 Telephone jacks Virgin Media junction box NT

As Check In + Front panel of telephone jack is bowing inwards and gapping Additional telephone jack seen Maintenance - Landlord xplain/Remove - Tenant



Ref # 7.12

7.13 Brass and black plastic switches and sockets as fitted

Woodwork

7.14 Skirting

Painted white wood Brass doorstop with black rubber tip Angle chips in places

As Check In + Shading RHS of radiator Scattered residue marks Doorstop tip detached and seen on floor Light debris Furniture indentations Fraying to edges FWT Clean - Tenant







Ref # 7.14

Ref # 7.14

Ref # 7.14



Ref # 7.14

Flooring

7.15 Fitted carpet

Blue fabric Brass threshold strip Faint discoloured patch to centre room

As Check In







Ref # 7.15



Ref # 7.15



Ref # 7.15

Page 31 of 54 123 London Road, N1 0PP

8. Bathroom







Ref #8

Item	Description	Condition at Check In	Condition at Check Out
Door & Architrave			
8.1 Door	Painted white wood 4 Recessed panels	Painted over defects Door does not remain closed Light rub to mid level RHS exterior Light finger soiling to interior	As Check In + Door now closes but with gapping between door and door frame Repair marks and touch up marks seen to closing edge and to mid level exterior Further light rubs seen Split seen above latch bolt to opening edge Explain/Repair - Tenant FWT



Ref # 8.1



Ref # 8.1



Ref # 8.1

8.2 Door Frame

Painted white wood

Painted over defects Minor mark high level RHS interior As Check In + Multiple removal holes to exterior edges Paint flaking and chips

Explain/Repair - Tenant

FWT

8. Bathroom (Cont.)







8.2

Door	Fixtures
DOOL	rixtures

8.3 Pair of lever handles with matching cuffs and integrated twist lock

Chrome

Light finger soiling Slightly loose

As Check In

8.4 Twist lock

Chrome

WO Slightly stiff As Check In

8.5 Over door hanger

Chrome and clear plastic

Item added after Check In

Not previously mentioned

Ceiling

8.6 Ceiling

Painted white

Screw and chipping near smoke detector Paint flaking and discolouration above window

As Check In + Further paint flaking and minor paint chips to protruding section forward of window FWT





Ref # 8.6

Ref # 8.6

Ceiling Mounted

8.7 Ceiling rose with cable, pendant and bulb White plastic

WO

Bulb not seen

Replace Bulb - Tenant

8.8 Smoke detector

White plastic

Tested and in WO

As Check In

Page 33 of 54 123 London Road, N1 0PP

8. Bathroom (Cont.)



Ref # 8.8

8.9 Bulk light	Chrome and obscure plastic	WO	As Check In
Walls			
8.10 Part painted	White	Light finger soiling in places Painted over defect to mid level behind door 'Circuit Details' sheet stuck to high level	As Check In + Light rubs Paint cracking to section RHS of toilet FWT

Ref # 8.10



Ref # 8.10

8.11 Part tiled

Grey tiles with white grouting with white plastic trim



Ref # 8.11




Ref # 8.11




Ref # 8.11

8. Bathroom (Cont.)



Ref # 8.11

Wall mounted fixtures			
8.12 Vents	2 Painted over		
8.13 Fuse box	White plastic	Excess paint	As Check In
8.14 Electric meter	Black plastic	Excess paint	As Check In
8.15 Door bell chime	Painted white over metal	WO	As Check In
8.16 'Danger' junction box	Grey metal	Excess paint	As Check In
8.17 Mirror	Unframed Integrated light strip Covered shavers only socket	Light in WO	As Check In + Chip to bottom RHS corner of mirror Light splash marks FWT Clean - Tenant
8.18 Access panel	White plastic	Cover seen open	As Check In
8.19 Shelves	3 Light wood White metal brackets	Item added after Check In	Not previously mentioned Explain/Remove - Tenant



Ref # 8.19

Windows and Frames

8.20 Window casement

Painted white metal 1 Fixed pane 1 Movable pane Chrome lever handle Obscure glass Cracks to 1 pane
White run marks
White discolouration to edges
No catch seen for handle

As Check In +
Paint chips FWT



Ref # 8.20

8.21 Reveals

As walls

Light water marks

As Check In + White residue spots Clean - Tenant



Ref # 8.21

8.22 Sills

Tiled as walls

Light debris

As Check In + White residue spots Clean - Tenant



Ref # 8.22

Heating

Page 36 of 54 123 London Road, N1 0PP

Ref # 8.26

8. Bathroom (Cont.)	1		
8.23 Ladder style heated towel rail	Chrome	Light excess paint Light dust to recesses	As Check In
Switches & Sockets			
8.24 Chrome and white plastic switches and sockets as fitted to include:	Shavers only socket	Excess paint Builders dust	As Check In
Flooring			
8.25 Flooring	Grey wood-effect laminate		Light debris White residue Clean - Tenant
Ref # 8	3.25 Ref :	# 8.25	Ref # 8.25
Toilet			
8.26 Toilet	White ceramic Chrome push button flush	WO Light residue to interior of bowl	As Check In + Hair residue to rear of lid Light soiling Tape to flush Clean - Tenant Explain/Remove - Tenant

Ref # 8.26

Ref # 8.26



Ref # 8.26

8.27 Seat and lid

White plastic

Loose

As Check In + Light soiling Clean - Tenant







Ref # 8.27

Basin

8.28 Basin

White ceramic Chrome waste, overflow, and pop up plug

Plug cover seen detached

As Check In + Plug now seen in situ Light soiling Split to edge of overflow

Clean - Tenant

Explain/Repair - Tenant



Ref # 8.28



Ref # 8.28

8.29 Taps

Chrome mixer tap with single temperature adjustor

Light water marks Green discolouration and light limescale to tap

As Check In

8.30 Vanity Unit

White laminate flip front door 1 Drawer Chrome D-handles Builders debris Rear wall unfinished plaster Metal washers and miscellaneous fixtures to drawer Brown water stain beneath pipe As Check In +
Hair residue
Brown stains to base of top
section
Miscellaneous items to interior

Clean - Tenant

Explain/Remove - Tenant







Ref # 8.30



Ref # 8.30

Bath / Shower

8.31 Bath

White plastic Chrome fixtures Light soiling
Hair residue
White residue below shower
screen
Splits to white insert of overflow

Evalois/Bossis Tosos




Ref # 8.31



Ref # 8.31



Ref # 8.31



Ref # 8.31



Ref # 8.31

Page 39 of 54 123 London Road, N1 0PP

8.32 Mixer tap with dual temperature adjusters	Chrome	Light water marks Limescale	As Check In			
8.33 Shower head and flex	Chrome and grey plastic					
8.34 Shower head bracket	Chrome					
8.35 Shower screen	Tempered glass Chrome trim Clear plastic seal	Light water marks	As Check In			
Appliances						
8.36 Washing machine	Montpelier Model no.: MTL6120W White 1 Dial Display panel Top opening	Manual and grey plastic fixture in situ	As Check In + Manual and grey plastic fixtures not seen Dust to recesses Explain/Replace - Tenant Clean - Tenant			
Furnishings and Content	Furnishings and Contents					
8.37 Toilet brush and holder	Chrome					
8.38 Hand wash		In use	As Check In			

Page 40 of 54 123 London Road, N1 0PP

9. Bedroom





Item	Description	Condition at Check In	Condition at Check Out

Door & Architrave

9.1 Door Pained white wood Finger soiling Clean - Tenant







9.2 Door Frame Painted white Minor residue spot to interior high level LHS Clean - Tenant

Door Fixtures

9.3 Pair of lever handles with matching backplates

Chrome

Very loose and detaching when used

Maintenance - Landlord



Page 41 of 54 123 London Road, N1 0PP

9. Bedroom (Cont.)

9. Beardonn (Cont.)			
9.4 Mortice lock with circular surround	Chrome	2 Keys in situ	As Check In
Ceiling			
9.5 Ceiling	Painted white		Minor black mould spots to corner LHS of window Clean - Tenant
	Ref	# 9.5	
Ceiling mounted fixtures			
9.6 Ceiling rose, cord, pendant, bulb and shade	White plastic White paper shade with pink motif	WO Cord discoloured Heat shading to pendant	As Check In
Walls			
9.7 Painted	White	Not fully examined due to furnishings Furnishings Light marks Orange spot marks	As Check In + Shrinkage cracking to far LHS of entry to low level FWT
	Ref	# 9.7	
Wall mounted fixtures			
9.8 Curtain hooks	2 Chrome		
Windows & Frames			

Page 42 of 54 123 London Road, N1 0PP

9. Bedroom (Cont.)

9.9 Window casement

White uPVC 3 Fixed panes 3 Movable panes Chrome lever handle with lock Exterior weather soiling and smears Mould to recesses Tarnishing to handles Condensation to lower panes As Check In + Mould now seen as heavier Clean - Tenant







Ref # 9.9

9.10 Reveals

As walls

9.11 Sill

Painted white wood

Light dust to top

As Check In + Dust no longer seen

Window Coverings

9.12 Curtains

Chrome curtain rail Pair of floor length grey fabric curtains

Light usage marks to rear of one FWT



Ref # 9.12

111		40.	
п	ea	ш	ng

9.13 Single panelled radiator

Painted white metal

NTBoth end caps seen As Check In

Switches & Sockets

9.14 White plastic switches and sockets as fitted

Usage marks Minor excess paint As Check In

Woodwork

Page 43 of 54 123 London Road, N1 0PP

9. Bedroom (Cont.)

9.15 Skirting	Painted white wood	Not fully examined due to furnishings Light marks Small splash mark forward of entry	As Check In
Flooring			
9.16 Fitted carpet	Brown fabric	Not fully examined due to furnishings Furniture indentations Wear to areas of tread	As Check In
Built In Cupboard			
9.17 Door, frame and fittings	Pained white wood doors and frame Chrome finger pulls 4 Unframed mirrors to interior of door		
9.18 Built in cupboard interior	Ceiling - painted white Walls - painted white Skirting - painted white wood Flooring - continuation from room	Light shrinkage cracking above skirting Furniture indentations to flooring Removal holes by hanging rail Orange spot marks	As Check In
9.19 Built in cupboard contents	White painted wooden shelf	Bowing slightly	As Check In
Furnishings			
9.20 Double bed frame with headboard	Medium wood-effect laminate		
9.21 Double mattress	White fabric		Discolouration FWT
	Ref # 9.21	Ref # 9.21	

Page 44 of 54 123 London Road, N1 0PP

Ref	Action Required	Responsibility	Comments
4.1 Front Entrance » Door	Explain/ Repair	Tenant	Soil spots Discolouration Marks in places 2 Removal holes above lock Indents to mid level opening edge Scratches above lock Sticker residue to opening edge
4.1 Front Entrance » Door	FWT	N/A	Soil spots Discolouration Marks in places 2 Removal holes above lock Indents to mid level opening edge Scratches above lock Sticker residue to opening edge
4.1 Front Entrance » Door	Clean	Tenant	Soil spots Discolouration Marks in places 2 Removal holes above lock Indents to mid level opening edge Scratches above lock Sticker residue to opening edge
4.2 Front Entrance » Door Frame	FWT	N/A	Scattered angle chips
4.4 Front Entrance » Lever handle	Explain/ Replace	Tenant	Not seen
4.7 Front Entrance » Mortice lock	Explain/ Remove	Tenant	Not previously mentioned
4.8 Front Entrance » Door	Explain/ Repair	Tenant	Rubs below lock Silvering low level Circular indents and 2 removal holes below night latch
4.8 Front Entrance » Door	FWT	N/A	Rubs below lock Silvering low level Circular indents and 2 removal holes below night latch
4.9 Front Entrance » Door Frame	FWT	N/A	Painted over defects Occasional light rubs Angle chips Light scuffs
4.11 Front Entrance » Doorknob	Explain/ Replace	Tenant	Not seen
4.12 Front Entrance » Mortice lock	Explain/ Replace	Tenant	Now seen as chrome twist lock

Page 45 of 54 123 London Road, N1 0PP

4.14 Front Entrance » Night latch and catch	Explain/ Remove	Tenant	Not previously mentioned
5.6 Entrance Hallway » Walls	FWT	N/A	Rub marks mid to low level LHS Rubs to RHS of bedroom 1 Rubs to RHS of entrance
5.7 Entrance Hallway » Entry phone	Clean	Tenant	NT Light dust
<u>5.8</u> Entrance Hallway » White plastic switches and sockets as fitted to include:	Clean	Tenant	Minor dust to top
5.9 Entrance Hallway » Skirting	Clean	Tenant	Light to moderate dust to top
5.11 Entrance Hallway » Door, frame and fittings	FWT	N/A	Indentation to LHS of door frame Rub marks to centre door frame
5.12 Entrance Hallway » Built in cupboard interior	FWT	N/A	Not fully examined due to height Rub marks throughout Dust to top of skirting
5.12 Entrance Hallway » Built in cupboard interior	Clean	Tenant	Not fully examined due to height Rub marks throughout Dust to top of skirting
5.13 Entrance Hallway » Built in cupboard contents	Explain/ Remove	Tenant	Smoke alarm tested and in WO Hangers in situ
6.1 Kitchen » Door	Clean	Tenant	Painted over defects Blue marks above exterior handle Small angle chip to mid level opening edge Faint splash marks to mid level exterior
6.1 Kitchen » Door	FWT	N/A	Painted over defects Blue marks above exterior handle Small angle chip to mid level opening edge Faint splash marks to mid level exterior
6.2 Kitchen » Door Frame	Clean	Tenant	Painted over defects Scattered residue spots Angle chip to high level RHS
6.2 Kitchen » Door Frame	FWT	N/A	Painted over defects Scattered residue spots Angle chip to high level RHS
6.3 Kitchen » Lever handle	FWT	N/A	White paint spots Scratches Residue to interior handle

Page 46 of 54 123 London Road, N1 0PP

6.3 Kitchen » Lever handle	Clean	Tenant	White paint spots Scratches Residue to interior handle
6.8 Kitchen » Painted	Clean	Tenant	Tape residue to high level between built in cupboards Brown soil spots to mid level between built in cupboards Shading to same area Further tape residue RHS to window Further tape residue, filled in hole and splash marks LHS to cooker hood Light rubs below light switch Heavy residue marks and soil spots below cooker hood
6.8 Kitchen » Painted	FWT	N/A	Tape residue to high level between built in cupboards Brown soil spots to mid level between built in cupboards Shading to same area Further tape residue RHS to window Further tape residue, filled in hole and splash marks LHS to cooker hood Light rubs below light switch Heavy residue marks and soil spots below cooker hood
6.8 Kitchen » Painted	Explain/ Repair	Tenant	Tape residue to high level between built in cupboards Brown soil spots to mid level between built in cupboards Shading to same area Further tape residue RHS to window Further tape residue, filled in hole and splash marks LHS to cooker hood Light rubs below light switch Heavy residue marks and soil spots below cooker hood
6.10 Kitchen » Extractor fan	Clean	Tenant	Soiling
6.12 Kitchen » Window casement	FWT	N/A	Excess paint Brown discolouration to frames Light soiling to handles and trickle vents
6.12 Kitchen » Window casement	Clean	Tenant	Excess paint Brown discolouration to frames Light soiling to handles and trickle vents
6.16 Kitchen » White plastic switches and sockets as fitted to include:	Clean	Tenant	Light soiling spots
6.18 Kitchen » Tiles	FWT	N/A	Light debris to floor Furniture indentations below fridge Rucking below washing machine and forward of kickboards
6.19 Kitchen » Kitchen units	FWT	N/A	Slight swelling and discolouration to edge of wall unit LHS of cooker hood
6.20 Kitchen » Wall units	FWT	N/A	Light usage marks

Page 47 of 54 123 London Road, N1 0PP

6.21 Kitchen » Base units	FWT	N/A	Light usage marks Faint discolouration to rear wall of under side unit Bowing, swelling and debris to under sink unit shelf
6.21 Kitchen » Base units	Explain/ Repair	Tenant	Light usage marks Faint discolouration to rear wall of under side unit Bowing, swelling and debris to under sink unit shelf
6.21 Kitchen » Base units	Clean	Tenant	Light usage marks Faint discolouration to rear wall of under side unit Bowing, swelling and debris to under sink unit shelf
6.22 Kitchen » Drawers	FWT	N/A	Light usage marks
6.23 Kitchen » Worktop	Clean	Tenant	Mould to sealant behind sink
6.25 Kitchen » 1 Sink with integrated dish drainer, overflow, waste, chain and plug	Clean	Tenant	Water marks Sponges to interior
6.25 Kitchen » 1 Sink with integrated dish drainer, overflow, waste, chain and plug	Explain/ Remove	Tenant	Water marks Sponges to interior
6.26 Kitchen » Mixer tap with single control	Clean	Tenant	Water marks
6.27 Kitchen » Cooker hood	Replace Bulb	Tenant	Fan and lights in WO Loose to wall 1 Bulb NW
6.29 Kitchen » Oven	Clean	Tenant	NT Light chip to top
6.30 Kitchen » Fridge freezer	Clean	Tenant	NT Light food residue in places Cracks to shelf to panel
6.30 Kitchen » Fridge freezer	Explain/ Repair	Tenant	NT Light food residue in places Cracks to shelf to panel
6.31 Kitchen » Washing machine	Clean	Tenant	NT Soap residue to tray Light soiling to exterior
6.32 Kitchen » Boiler	Clean	Tenant	NT Light residue to front and side
6.33 Kitchen » Door, frame and fixtures	Clean	Tenant	Scattered residue spots and dark marks Angle chip to opening edge of LHS cupboard door

Page 48 of 54 123 London Road, N1 0PP

6.33 Kitchen » Door, frame and fixtures	FWT	N/A	Scattered residue spots and dark marks Angle chip to opening edge of LHS cupboard door
6.34 Kitchen » Built in cupboard interior	Explain/ Remove	Tenant	Wear 3 Screws to walls of LHS built-in cupboard
6.36 Kitchen » Additional items	Explain/ Remove	Tenant	Not previously mentioned
7.1 Reception » Door	FWT	N/A	Occasional paint chips Scratches to mid level exterior Light finger marks above interior handle Drip marks below interior handle
7.1 Reception » Door	Clean	Tenant	Occasional paint chips Scratches to mid level exterior Light finger marks above interior handle Drip marks below interior handle
7.3 Reception » Pair of lever handles with matching backplates	Maintenance	Landlord	Usage marks Tarnished Loose Paint chips
7.3 Reception » Pair of lever handles with matching backplates	FWT	N/A	Usage marks Tarnished Loose Paint chips
7.7 Reception » Painted	Explain/ Repair	Tenant	Several pin holes to high level LHS of chimney breast Filled in removal hole to high level RHS of entry Notable angle chip to mid level RHS of window Notable discolouration below window Rubs in places Notable tears to corner RHS of entry door Further scattered small tears to lining paper Several pin holes to mid level throughout White plastic hook to RHS edge of recess RHS of entry door <i>Water penetration stains below window</i>
7.7 Reception » Painted	Explain/ Remove	Tenant	Several pin holes to high level LHS of chimney breast Filled in removal hole to high level RHS of entry Notable angle chip to mid level RHS of window Notable discolouration below window Rubs in places Notable tears to corner RHS of entry door Further scattered small tears to lining paper Several pin holes to mid level throughout White plastic hook to RHS edge of recess RHS of entry door <i>Water penetration stains below window</i>
7.10 Reception » Venetian blinds	Explain/ Repair	Tenant	WO Light discolouration, dust and residue marks to slats, cords, acorns and rod One acorn broken and seen to floor Crack to 1 slat to mid level RHS

7.12 Reception » White plastic switches and sockets as fitted to include:	Maintenance	Landlord	NT Front panel of telephone jack is bowing inwards and gapping Additional telephone jack seen
7.12 Reception » White plastic switches and sockets as fitted to include:	Explain/ Remove	Tenant	NT Front panel of telephone jack is bowing inwards and gapping Additional telephone jack seen
7.14 Reception » Skirting	FWT	N/A	Angle chips in places Shading RHS of radiator Scattered residue marks Doorstop tip detached and seen on floor Light debris Furniture indentations Fraying to edges
7.14 Reception » Skirting	Clean	Tenant	Angle chips in places Shading RHS of radiator Scattered residue marks Doorstop tip detached and seen on floor Light debris Furniture indentations Fraying to edges
8.1 Bathroom » Door	Explain/ Repair	Tenant	Painted over defects Door does not remain closed Light rub to mid level RHS exterior Light finger soiling to interior Door now closes but with gapping between door and door frame Repair marks and touch up marks seen to closing edge and to mid level exterior Further light rubs seen Split seen above latch bolt to opening edge
8.1 Bathroom » Door	FWT	N/A	Painted over defects Door does not remain closed Light rub to mid level RHS exterior Light finger soiling to interior Door now closes but with gapping between door and door frame Repair marks and touch up marks seen to closing edge and to mid level exterior Further light rubs seen Split seen above latch bolt to opening edge
8.2 Bathroom » Door Frame	Explain/ Repair	Tenant	Painted over defects Minor mark high level RHS interior Multiple removal holes to exterior edges Paint flaking and chips
8.2 Bathroom » Door Frame	FWT	N/A	Painted over defects Minor mark high level RHS interior Multiple removal holes to exterior edges Paint flaking and chips
8.6 Bathroom » Ceiling	FWT	N/A	Screw and chipping near smoke detector Paint flaking and discolouration above window Further paint flaking and minor paint chips to protruding section forward of window

Page 50 of 54 123 London Road, N1 0PP

8.7 Bathroom » Ceiling rose with cable, pendant and bulb	Replace Bulb	Tenant	Bulb not seen
8.10 Bathroom » Part painted	FWT	N/A	Light finger soiling in places Painted over defect to mid level behind door 'Circuit Details' sheet stuck to high level Light rubs Paint cracking to section RHS of toilet
8.17 Bathroom » Mirror	FWT	N/A	Light in WO Chip to bottom RHS corner of mirror Light splash marks
8.17 Bathroom » Mirror	Clean	Tenant	Light in WO Chip to bottom RHS corner of mirror Light splash marks
8.19 Bathroom » Shelves	Explain/ Remove	Tenant	Not previously mentioned
8.20 Bathroom » Window casement	FWT	N/A	Cracks to 1 pane White run marks White discolouration to edges No catch seen for handle Paint chips
8.21 Bathroom » Reveals	Clean	Tenant	Light water marks White residue spots
8.22 Bathroom » Sills	Clean	Tenant	Light debris White residue spots
8.25 Bathroom » Flooring	Clean	Tenant	Light debris White residue
8.26 Bathroom » Toilet	Clean	Tenant	WO Light residue to interior of bowl Hair residue to rear of lid Light soiling Tape to flush
8.26 Bathroom » Toilet	Explain/ Remove	Tenant	WO Light residue to interior of bowl Hair residue to rear of lid Light soiling Tape to flush
8.27 Bathroom » Seat and lid	Clean	Tenant	Loose Light soiling
8.28 Bathroom » Basin	Clean	Tenant	Plug cover seen detached Plug now seen in situ Light soiling Split to edge of overflow

Page 51 of 54 123 London Road, N1 0PP

8.28 Bathroom » Basin	Explain/ Repair	Tenant	Plug cover seen detached Plug now seen in situ Light soiling Split to edge of overflow
8.30 Bathroom » Vanity Unit	Clean	Tenant	Builders debris Rear wall unfinished plaster Metal washers and miscellaneous fixtures to drawer Brown water stain beneath pipe Hair residue Brown stains to base of top section Miscellaneous items to interior
8.30 Bathroom » Vanity Unit	Explain/ Remove	Tenant	Builders debris Rear wall unfinished plaster Metal washers and miscellaneous fixtures to drawer Brown water stain beneath pipe Hair residue Brown stains to base of top section Miscellaneous items to interior
8.31 Bathroom » Bath	Clean	Tenant	Light soiling Hair residue White residue below shower screen Splits to white insert of overflow
8.31 Bathroom » Bath	Explain/ Repair	Tenant	Light soiling Hair residue White residue below shower screen Splits to white insert of overflow
8.36 Bathroom » Washing machine	Explain/ Replace	Tenant	Manual and grey plastic fixture in situ Manual and grey plastic fixtures not seen Dust to recesses
8.36 Bathroom » Washing machine	Clean	Tenant	Manual and grey plastic fixture in situ Manual and grey plastic fixtures not seen Dust to recesses
9.1 Bedroom » Door	Clean	Tenant	Finger soiling
9.2 Bedroom » Door Frame	Clean	Tenant	Minor residue spot to interior high level LHS
9.3 Bedroom » Pair of lever handles with matching backplates	Maintenance	Landlord	Very loose and detaching when used
9.5 Bedroom » Ceiling	Clean	Tenant	Minor black mould spots to corner LHS of window
9.7 Bedroom » Painted	FWT	N/A	Not fully examined due to furnishings Furnishings Light marks Orange spot marks Shrinkage cracking to far LHS of entry to low level

9.9 Bedroom » Window casement	Clean	Tenant	Exterior weather soiling and smears Mould to recesses Tarnishing to handles Condensation to lower panes Mould now seen as heavier
9.12 Bedroom » Curtains	FWT	N/A	Light usage marks to rear of one
9.21 Bedroom » Double mattress	FWT	N/A	Discolouration

Page 53 of 54 123 London Road, N1 0PP

Signed by the			
Signature			
Print Name			
Date	/	/	
Signed by the			
Signature			
Print Name			
Date	1	/	

Page 54 of 54 123 London Road, N1 0PP